


# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-219	Smoke	8/10/2009	ADS/TM	S19KK_045MH	Dry	Yes	403.72



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-219	Smoke	8/10/2009	ADS/TM	S19KK_045MH	Dry	Yes	403.72

### Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S19KK_021G1	S19KK_021MH	S19KK_004MH	214.795	10
S19KK_045G1	S19KK_045MH	S19KK_021MH	60.2569	8
S19KK_015G1	S19KK_015MH	S19KK_045MH	128.668	8

### Observations & Photos

**Obs\_ID** S1028-219-OB01

**Address** 2029 Payson St


**Status** Public

**Source** Catch Basin

**Location** Curb

**Nearest MH** S19KK\_021MH

**Comments** Smoke from catch basin along curb. 2029 Payson St.



**Picture** \S1028-219-OB01-P01.jpg

**Comments** Payson St. & Clifton Ave. looking northeast

**Obs\_ID** S1028-219-OB02

**Address** 2028 Payson St

**Status** Public

**Source** Catch Basin

**Location** Curb

**Nearest MH** S19KK\_021MH

**Comments** Smoke from catch basin along curb. 2028 Payson St.



**Picture** \S1028-219-OB02-P01.jpg

**Comments** Payson St. & Clifton Ave. looking west

---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-219	Smoke	8/10/2009	ADS/TM	S19KK_045MH	Dry	Yes	403.72

**Obs\_ID** S1028-219-OB03

**Address** Payson St. & Clifton Ave.


**Status** Public

**Source** Catch Basin

**Location** Curb

**Nearest MH** S19KK\_045MH

**Comments** Smoke from catch basin along curb.  
Northwest corner of Payson St. & Clifton Ave.



**Picture** \S1028-219-OB03-P01.jpg

**Comments** Payson St. & Clifton Ave. looking  
northeast

